



This is not double switching. This means that the TRF is now operating in discontinuous mode.

There is something wrong in the IDS waveform. I have not encountered this IDS waveform. Please check your set up.

Correct IDS waveform is show below.

